

**DEPARTMENT OF THE ARMY TECHNICAL MANUAL
DEPARTMENT OF THE AIR FORCE TECHNICAL ORDER**

**RADIO RECEIVERS BC-312, -A, -C, -D, -E, -F, -G, -J, -L, -M,
-N, -HX, AND -NX; BC-342, -A, -C, -D, -F, -J, -L, -M, AND
-N; BC-314, -C, -D, -E, -F, AND -G; BC-344 AND -D, AND
RADIO RECEIVER ASSEMBLIES OA-65/MRC-2 AND
OA-65A/MRC-2**

TM 11-850
TO 31R2-3BC-111
CHANGES No. 4

DEPARTMENTS OF THE ARMY
AND THE AIR FORCE
WASHINGTON 25, D. C., 14 March 1958

TM 11-850/TO 31R2-3BC-111, 3 September 1946, is changed as follows:

Note. The parenthetical reference to previous changes (example: "page 5 of C 2") indicates that pertinent material was published in that change.

Page 8, paragraph 6. Add the following note after the paragraph:

Note. In Radio Receivers BC-312, BC-312-A, BC-312-C, BC-314-C, BC-342-A, BC-342-C, and BC-344, Mounting FT-162 is replaced with Mounting FT-162-A.

Page 16, paragraph 12d. Delete the last sentence (page 1 of C 3) and substitute:

Check Fuse FU-27 (2-ampere) in Rectifier RA-20, and the two fuses (2-ampere and 1/4-ampere) in Power Supply PP-1499/G.

Page 19, paragraph 13k. Delete the last sentence (page 2 of C 3) and substitute:

In addition to the above fuses, there is a 2-ampere fuse in Rectifier RA-20 and two fuses, 2-ampere and 1/4-ampere, in Power Supply PP-1499/G.

Page 20, paragraph 15.1a (page 1 of C 2). Delete subparagraph (3) and substitute:

(3) Operate the OFF-MVC-AVC control to MVC and adjust the VOL control for best reception. Repeat the instructions in (1) above. The desired signal may become readable.

Page 71, figure 32.2 (page 3 of C 3). Change F2, 1/8 AMP to F2, 1/4 AMP.

Page 71, figure 70.2 (page 5 of C 3). Add the following note:

NOTE:

THE PANEL MARKING FOR FUSE F2 SHOULD BE 1/4 AMP.

Page 131, appendix I. Delete.

Page 142, appendix III. (*Page 25, paragraph 7, C 1*). Delete.

TM 11-850
 TO 31R2-3BC-111
 C 4

BY ORDER OF THE SECRETARIES OF THE ARMY AND THE AIR FORCE:

MAXWELL D. TAYLOR,
*General, United States Army,
 Chief of Staff.*

OFFICIAL:

HERBERT M. JONES,
*Major General, United States Army,
 The Adjutant General.*

THOMAS D. WHITE,
Chief of Staff, United States Air Force.

OFFICIAL:

J. L. TARR,
*Colonel, United States Air Force,
 Director of Administrative Services.*

DISTRIBUTION:

Active Army:

ASA	Br Svc Sch	USA Elct Pg
CNGB	Gen Depots	Sig Fld Maint Shops
Technical Stf, DA	Sig Sec, Gen Depots	Sig Lab
Technical Stf Bd	Sig Depots	Mil Dist
USA Arty Bd	Fld Comd, AFSWP	JBUSMC
USA Armor Bd	Engr Maint Cen	Units organized
USA Inf Bd	Army Pictorial Cen	under following
USA Air Def Bd	USA SpWar Cen	TOE's:
USA Abn & Elct Bd	WRAMC	5-345
USA Avn Bd	AFIP	5-526
USA Armor Bd Test	AMS	11-7
Sec	Port of Emb (OS)	11-16
USA Air Def Bd Test	Trans Terminal	11-57
Sec	Comd	11-95
USA Arctic Test Bd	Army Terminals	11-98
USCONARC	OS Sup Agcy	11-127
US ARADCOM	USA Sig Pub Agcy	11-128
OS Maj Comd	USA Sig Comm Engr	11-500 (AA-AE)
Log Comd	Agcy	11-557
MDW	USA Comm Agcy	11-587
Armies	TASSA	11-592
Corps	USA Sig Eqp Spt	11-597
Div	Agcy	32-500
USATC	USA White Sands Sig	44-70
Ft & Camp	Agcy	44-201
Svc Colleges	Yuma Test Sta	

NG: State AG; units—same as Active Army.

USAR: None.

For explanation of abbreviations used, see AR 320-50.

TAGO 4791B

U. S. GOVERNMENT PRINTING OFFICE: 1959